



*Huntington Specialty Materials*

**Application Guide**

**HS-920 Mold Tooling Sealer Coat**

**Nano-Ceramic Clear (wipe-on) ----- “No Free Silicones - Zero transfer”**

HS-920 is a high performance • single component • wipe-on • ambient air cured product  
HS-920 creates a covalent bond to the substrate giving it an intrinsic bond to the mold tool  
HS-920 is an inert (benign) material containing no “Free Silicones” • No dimensional change  
HS-920 soaks into the micro pores & micro-cracks sealing them permanently, from the face side  
HS-920 saves expensive leaking Graphite, Composite and all types of Metal molds and tooling,  
(\*examples; Epoxies, BMIs, Polyimides and similar high temperature cured resin systems)




HS-920 Mold Tool Sealer was formulated for simple application & high performance results.

**Note!** Surfaces must be free from oils and other contaminants before starting the coating process.

**Application on Metal, Graphite or Composites Molds & Tooling;**

- Mix contents gently before applying to ensure that is no separation of the resin system.
- With clean dry air blow off any dust from the surfaces, preventing contaminating the coating.
- **Coating the face side of the Mold Tool:**
  - ✓ Apply a modest amount of the coating on the surface or on a lint free pad or cloth
  - ✓ In a circular motion work the release coating into the surface of the mold tool
  - ✓ Once the absorption seems to stop, gently glide the wetted applicator over the surface to ensure that there is a complete coverage with a semi-wet 2-5 micron of the coating on the entire surface of the mold tool.
  - ✓ Let the coated surface, ambient dry to a “Dry to the Touch” film, a warm 110°F/43°C (max) air flow will speed this up.
  - ✓ Allow the coated surface to cross-link for 2-3 hrs or longer, it is now ready to be heated or put into a convection oven or autoclave at (350°F - 30 min part temp) to cure further cure the resins that are within the mold tools Nano-porous face.
  - ✓ **Do not** put parts in an oven to cure – prior to the 2-3 hrs or the solvents will expand and potentially create minute pin-holes within the embedded coating during this cure.
  - ✓ **Allow the part to cool – before applying a coating of the HS-940 Release coating**



Manufacturer is not responsible for the use and application of this material. It is up to the end user determine the suitability of this product for their own application. It is the belief that the contents of this document we- accurate at the time of printing. No warranty is written or implied regarding application and use of this product.